

Newly added Drive / Updated Firmware
 Media can be burned and play-back completely with the same writer
 Do not support the media as writer max speed
 Writing or Playback incompletely
 Drive Not Support ProdiscF02 code

DVD-R Compatibility

Writer Type	PC Writer	AV Recorder	DVD-R Burner's Max Speed	MID F/W	4X	8X		16X	New Firmware Time
					S03	S04	F01	F02	
HLDS	GSA-4163B		16X	A103	4X	8X	8X	4X	2005-03-04
NEC	ND-3500A		16X	2.19	4X	8X	8X	16X	2005-03-16
	ND-3520A		16X	1.24	4X	8X	8X	16X	
PHILIPS	DVDR1640P		16X	P3.4	4X	12X	12X	16X	2005-02-18
PIONEER	DVR108		16X	1.18	4X	8X	8X	16X	
	DVR109		16X	1.40	4X	8X	8X	12X	2005-03-25
PLEXTOR	PX-716A		16X	1.04u	4X	8X	8X	12X	2005-02-21
RICOH	MP5316DA		16X	2.B9	4X	8X	8X	-	
SONY	DRU-720A		16X	JY02	4X	8X	8X	16X	2005-02-14
TSST (Buffalo)	TS-H552A		16X	BA53	4X	8X	8X	4X	2005-01-10
	DW1610		16X	B8T9	4X	12X	12X	16X	2005-01-17
BENQ	DW1620		16X	B7T9	4X	12X	12X	16X	
	DW1620		16X	B7U9	4X	8X	8X	8X	2005-02-23
BTC	DVDRW 1016 IM		16X	A07R	4X	8X	8X	16X	2005-03-04
CYBER	DX162D-A		16X	120F	4X	8X	8X	16X	
LITEON	SOHW-1673S		16X	JS02	4X	8X	8X	16X	2005-02-14
MSI	DR16-B2		16X	M1.6	4X	12X	12X	16X	2005-01-10
NU	DDW-163		16X	G7P9	4X	12X	12X	16X	
OPTORITE	DD1601		16X	16AF	2X	4X	8X	16X	
TSST (SAMSUNG)	TS-H552B		12X	TS08	4X	8X	8X	12X	2005-03-21
SONY	DRU-710A		12X	BYX3	4X	8X	8X	8X	2005-02-21
TOSHIBA	SD-R5372		12X	TU55	4X	8X	8X	4X	2005-03-18
LITEON	SOHW-1653S		12X	CS0G	4X	8X	8X	8X	2005-03-07
	GSA-4082B		8X	A207	4X	8X	4X	4X	
HLDS	GSA-4120B		8X	A115	4X	8X	8X	4X	2005-01-15
	GSA-4160B		8X	A304	4X	8X	8X	4X	2005-02-18
	DVD 420n		8X	1.33	4X	8X	8X	8X	
HP	DVD 540b		8X	110i	4X	8X	8X	4X	
	DVD 630c		8X	CH16	4X	8X	8X	8X	2005-03-11
MEMOREX	True8xn		8X	1.G2	4X	8X	8X	-	
	ND-2500A		8X	1.0A	4X	8X	8X	8X	2005-03-18
NEC	ND-2510A		8X	2.18	4X	8X	8X	8X	2005-03-18
	ND-6500A		8X	2.24	4X	6X	8X	-	2005-03-18
	LF-P767		8X	1.01	4X	6X	2X	2X	2005-03-11
PANASONIC	LF-M721		8X	APP6	4X	8X	8X	4X	2005-02-25
	SW-9583S		8X	B100	2X	4X	4X	4X	
PANASONIC (I-O DATA)	UJ-835S		8X	GZM5	2X	2X	2X	2X	2005-01-28
PIONEER	DVR-107D		8X	1.21	4X	4X	8X	4X	
PLEXTOR	PX-605A		8X	AKP2	4X	8X	8X	4X	2005-03-18
	PX-712A		8X	1.06	4X	8X	8X	8X	2005-02-16
RICOH	MP5308D		8X	1.B3	4X	8X	8X	-	
SAMSUNG	SH-W08A		8X	1S31	4x	4X	4X	4X	
TSST (SAMSUNG)	TS-H542A		8X	TS06	4X	8X	4X	4X	2005-03-07
	TS-L532A		8X	T151	4X	8X	4X	4X	2005-03-23
	DRU-530A		8X	2.1g	4X	8X	8X	4X	
SONY	DRU-540A		8X	1.0b	4X	8X	8X	4X	
	DRU-700A		8X	VY08	4X	8X	8X	8X	
TDK	DVDRW 880N		8X	1.36	4X	8X	8X	8X	2005-01-10
	AID+1280B		8X	T7S4	4X	8X	8X	8X	
TEAC	DV-W58D		8X	1.21	4X	4X	8X	4X	2005-03-01
	DV-W516G		8X	B4S6	4X	8X	8X	8X	
TOSHIBA	SD-R5272		8X	1031	4X	4X	4X	4X	
AOPEN	DUW1608/ARR		8X	A070	4X	8X	8X	8X	2005-01-28
ARTEC	VOM-12E48X		8X	100d	4X	8X	6X	6X	
BTC	DVDRW 1108 IM		8X	B330	4X	8X	8X	8X	2005-03-04
	SOHW-812S		8X	US0Q	4X	8X	8X	4X	
LITEON	SOHW-832S		8X	VS0G	4X	8X	8X	8X	2005-02-05
	SOHW-1213S		8X	TS0D	4X	6X	6X	4X	
	SOHW-1613S		8X	AS06	4X	8X	8X	8X	2005-03-11
	SOHW-1633S		8X	BS0S	4X	8X	8X	8X	
NU	DDW-082		8X	B375	4X	4X	4X	-	
	DD0405		8X	160E	4X	8X	8X	4X	
OPTORITE	DD1203		8X	120E	4X	8X	8X	4X	
	DD1205		8X	120e	4X	8X	8X	4X	
HLDS	GSA-4040B		4X	A304	4X	2X	2X	2X	
	GSA-4081B		4X	A104	4X	4X	4X	2X	
NEC	ND-1300A		4X	1.0B	4X	4X	4X	-	

Newly added Drive / Updated Firmware
 Media can be burned and play-back completely with the same writer
 Do not support the media as writer max speed
 Writing or Playback incompletely
 Drive Not Support ProdiscF02 code

DVD-R Compatibility

Writer Type	PC Writer	AV Recorder	DVD-R Burner's Max Speed	MID F/W	4X	8X		16X	New Firmware Time
					S03	S04	F01	F02	
PANASONIC	LF-P667		4X	1.02	4X	2X	2X	2X	
	LF-M621		4X	F100	4X	4X	4X	4X	
PHILIPS	DVDR824P		4X	P3.3	4X	4X	4X	4X	
PIONEER	DVR-105		4X	1.33	4X	4X	4X	4X	
	DVR-106D		4X	1.08	4X	4X	4X	4X	
PLEXTOR	PX-708A		4X	1.09	4X	4X	4X	4X	2005-02-05
SONY	DRU-500A		4X	2.1a	4X	4X	4X	4X	
	DRU-510A		4X	1.1a	4X	4X	4X	4X	
TDK	DVDRW 0404N		4X	1.0C	4X	4X	4X	-	
	DVDRW 840G		4X	1.08	4X	4X	4X	4X	
TEAC	DV-W50E		4X	1.30	4X	4X	4X	4X	
	DV-W50D		4X	1.07	4X	4X	4X	4X	
	DV-W58G		4X	H4S3	4X	2X	2X	2X	
TOSHIBA	SD-R5112		4X	1033	4X	1X	1X	1X	
BTC	DVDRW 1004 IM		4X	0151	4X	4X	4X	4X	
	DVDRW 1008 IM		4X	0159	4X	4X	4X	4X	
LITEON	LDW-411S		4X	FS0K	4X	2X	2X	2X	
	LDW-811S		4X	HS0R	4X	2X	2X	2X	
	LDW-851S		4X	GS0P	4X	4X	4X	4X	
MSI	DR8-A		4X	150D	4X	4X	4X	4X	
OPTORITE	DD0203		4X	2.50	4X	2X	2X	2X	
	DD0401		4X	160E	4X	8X	8X	4X	
HLDS	GMA-4020B		2X	A109	2X	2X	2X	2X	
PANASONIC	LF-D521		2X	A116	2X	2X	2X	2X	
	LF-P567		2X	E105	2X	2X	2X	2X	
PIONEER	DVR-103		2X	2.00	2X	2X	2X	2X	
	DVR-104		2X	1.40	2X	2X	2X	2X	
TOSHIBA	SD-R5002		2X	1033	1X	1X	1X	-	
	SD-R6112		2X	1M31	1X	1X	1X	-	
BENQ	Dual DW800A		2.4X	B3C7	2.4X	2.4X	2.4X	2.4X	
ASUS	DVR-104/2		2X	1.41	2X	2X	2X	2X	
PANASONIC	LF-D310		1X	A128	1X	1X	1X	-	
PIONEER	DVR-520H		8X (160GB)		4X	4X	8X	4X	
	DVR-720H-S		8X (250GB)		4X	4X	8X	4X	
TOSHIBA	RD-X5		8X (600GB)		4X	8X	8X	4X	
PANASONIC	DMR-E200H		4X (160GB)		4X	4X	4X	4X	
	DMR-E95H		4X (250GB)		4X	4X	4X	4X	
PIONEER	DVR-77H		4X (80GB)		4X	4X	4X	4X	
SONY	RDR-HX10		4X (250GB)		4X	4X	4X	4X	
	PSX(DESR-7000)		4X (160GB)		4X	4X	4X	4X	
TOSHIBA	RD-XS41		4X (160GB)		2X	2X	2X	2X	
	RD-X4		4X (250GB)		2X	2X	2X	2X	2005-03-04
SHARP	DV-HRD1		1X (80GB)		1X	1X	1X	1X	
JVC	DR-M1		1X		1X	1X	1X	1X	
LG	DR4810		1X		1X	1X	1X	1X	
PANASONIC	DMR-E20	1X		1X	1X	1X	1X		
	DMR-E30	1X		1X	1X	1X	1X		
	DMR-E50	1X		1X	1X	1X	1X		
	DMR-E55	1X		1X	1X	1X	1X	2005-03-04	
	DVR-3000	1X		1X	1X	1X	1X		
PIONEER	DVR-7000	1X		1X	1X	1X	1X		
	DVR-310-S	1X		1X	1X	1X	1X		
SONY	DCR-DVD300	1X		-	-	-	-		
	RDR-GX7	1X		1X	1X	1X	1X		
LITEON	LVW-5005	1X		1X	1X	1X	1X		
HITACHI	DZ-MV350	1X		-	-	-	-		
	DZ-MV380	1X		-	-	-	-		
	DZ-MV550	1X		-	-	-	-		

Test Environment
 CPU : INTEL Pentium2.4 GHz
 RAM : 512MB
 HD : 60 GB
 OS : Windows XP
 Burn software : Nero Burning ROM ver6.6.0.8
 Burn Image : Video Image 4.41GB